

LIEBHERR PR732L

INSPECTED

ENGINE : GOOD WORKING

PUMP : Pressure OK

U/C : Very used 90%

BLADE : OK 60% used

Leacks : Leacks have been repaired

Translation OK

Rotation OK

Electrical functions : OK

Dimensions : 5.5 x 2.85 x 3.24 m (removed blade)

Weight : 18.1 T

Note : 7/10