

KOMATSU PC60-5
1993/ S/N : 25279

INSPECTED

ENGINE : GOOD WORKING

PUMP : Pressure OK

U/C : used 50%

BUCKET : 3 BUCKETS standard teeth 80cm / 30cm + 1.5m curing OK 60% used

Leacks : very little leacks

Translation OK

Rotation OK

Electrical functions : OK

BODY : ORIGINAL PAINT

Dimensions : 6.08x 2.15 x 2.59 m

Weight : 6T

Note : 7/10

Old machine but still have all its functions