

DOOSAN DX140LCR-3
2014
3600H

INSPECTED

ENGINE: VERY GOOD WORKING
PUMP: Pressure OK

U/C: 30% used
BUCKET:3 buckets: 1100/ 600 and hydraulic tilt curing bucket
HYDRAULIC QH ARDENNE
Leacks: NO
A/C
Automatic Grease
PADS are 700mm

Translation OK
Rotation OK
Electrical functions: OK
ALL Hydraulic Lines
Monoboom

BODY: VERY BEAUTIFUL APPEARANCE

Dimensions: 7.19x 2.69x 3.09m
Weight: 15.3T