

CATERPILLAR 972 M XE
2015
8300H
S/N : 344

INSPECTED

ENGINE : VERY GOOD WORKING / TURBO/ NO LEACKS
PUMP : Pressure OK

JOYSTICK
Z KYNEMATICS
TIRES : 40% OK / 26.5 R 25 / MICHELIN XHA2
BUCKET : 3.4m /4800 L / TEETH Direct mounted
CENTRAL GREASE
A/C
REAR CAMERA
CENTRAL GREASE GROENVELD
Electronic balance CAT
PREFILTER
Electric REAR COVER

Leacks : No
Translation OK
Rotation OK
Electrical functions : OK

BODY : VERY GOOD APPEARANCE
CABINE IN VERY GOOD CONDITION

Observations : Bent right rear step Front left mudguards + left rear + right rear broken

Dimensions : 7.77 x 3 x 3.52m
Weight : 24.9T Tons

Machine is ready for work

Note : 8/10