

LIEBHERR LR 622

2001

4213H

S/N 392-5202

INSPECTED

ENGINE : VERY GOOD WORKING

PUMP : Pressure OK

U/C :50% OK

BUCKET : Standard teeth bucket

A/C

Ripper

Leacks : No

Translation : OK

Rotation OK

Electrical functions : OK

BODY : GOOD APPEARANCE

Dimensions : 6.12x 2.45 x 3.13m

Weight : 15.5 Tons

Observations : Machine with low hours good mechanically

Note : 7/10