

DOOSAN DX140LC

2014

3950H

Monoboom

CE Certificate

INSPECTED

ENGINE : VERY GOOD WORKING

PUMP : Pressure OK

Quick hitch

BUCKETS : Standard + hydraulic curing bucket

Security valves

Camera

A/C

Hammer line

Auxiliary line

Pads 700mm

U/C 50% OK

Leacks : no leacks

Translation OK

Rotation OK

Electrical functions : OK

BODY : VERY GOOD APPEARANCE

Dimensions : 7.69x 2.6 x 2.57 m

Weight : 14 Tons

Machine in very good working order

Note : 8/10