

KOMATSU D31S
1993
3800H

INSPECTED

ENGINE : VERY GOOD WORKING

PUMP : Pressure OK

U/C : 40% OK

BUCKET : 4X1 bucket

Leacks : No

Electrical functions : OK

BODY : GOOD APPEARANCE

Dimensions : 4.15 x 1.79 x 2.65m

Weight : 6.68Tons

Observations : Machine with low hours good mechanically

Note : 7/10